

# SL

Installation illustrate



Web : <https://www.mwworkstation.com/>

Tel : +86 13695211636

Mail : [robbor@mwworkstation.com](mailto:robbor@mwworkstation.com)

# Contents


|  |       |     |
|--|-------|-----|
| <a href="#"><u>Components Freestanding</u></a>   | ----- | 1P  |
| <a href="#"><u>Manager with side table</u></a>   | ----- | 3P  |
| <a href="#"><u>Manager with side cabinet</u></a> | ----- | 4P  |
| <a href="#"><u>Single side bench Double</u></a>  | ----- | 5P  |
| <a href="#"><u>side bench</u></a>                | ----- | 6P  |
| <a href="#"><u>L shape workstation</u></a>       | ----- | 8P  |
| <a href="#"><u>Extension bar</u></a>             | ----- | 12P |
| <a href="#"><u>Six side bench</u></a>            | ----- | 16P |
|  | ----- | 17P |

# SL

## Components

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### PARTS SHOW




# SL

## Components

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM




### PARTS SHOW



### INSTALLATION STEPS





#### Horizontal for frame

Round head cross screw M8\*12



#### Vertical for top

Round head cross screw M6\*16





# SL



## Manager with side table

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS





Countersunk cross topping  
screw M4\*16




Horizontal for frame

Round head cross screw M8\*12







[Modesty]





### INSTALLATION STEPS

#### Horizontal for frame

Round head cross screw M8\*12








M4\*16




#### Vertical for top

Round head cross screw M6\*16



[Modesty]



# SL




## Single side bench

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS




#### Horizontal for frame

Round head cross screw M8\*12





#### Vertical for top

Round head cross screw M6\*16



M4\*16

[H750 desk screen]








# SL

## Single side bench

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS




Countersunk cross topping  
screw M4\*16



### INSTALLATION STEPS




#### Horizontal for frame

Round head cross screw M8\*12



#### Vertical for top

Round head cross screw M6\*16



# SL




## Double side bench

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM


### INSTALLATION STEPS

#### STEP: ①



Countersunk cross topping  
screw M4\*16



#### STEP: ②



#### STEP: ③






# SL

## Double side bench

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS

Round head cross screw M6\*16




# SL

## Double side bench



FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS



STEP: ①

Countersunk cross topping  
screw M4\*16



STEP: ②

# SL



## L shape workstation

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM




### INSTALLATION STEPS

#### Horizontal for frame

Round head cross screw M8\*12



Round head cross screw M6\*16



# SL



## L shape workstation

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS

#### Vertical for top

Round head cross screw M6\*16






# SL


## L shape workstation

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM



### INSTALLATION STEPS



STEP: ①



STEP: ②



STEP: ③






# SL

## L shape workstation

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS

Countersunk cross topping  
screw M4\*16






# SL

## Extension bar

FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS




# SL

## Six side bench


FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS

STEP : ①



 CAUTION




# SL

## Six side bench



FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS

STEP : ②



STEP : ③



[ Countersunk cross topping  
screw M4\*16 ]


# SL

## Six side bench


FAST AND CONVENIENT INSTALLATION SYSTEM  
DESK SYSTEM SCREEN SYSTEM

### INSTALLATION STEPS


STEP : ④



Countersunk cross topping  
screw M6\*35



STEP : ⑤



# M & W

**Web:** [mwworkstation.com](http://mwworkstation.com)

**Mail:** [robbor@mwworkstation.com](mailto:robbor@mwworkstation.com)

**Tel:** +86 13695211636

**WhatsApp:** + 86 13695211636

**Add:** NO.3 Xingye North Road Dawotang Industrial  
District Shishan Nanhai Foshan City Guangdong  
P.R China



WhatsApp



Facebook



Instagram



Twitter



Pinterest



Linkein



YouTube