

VL

 Installation illustrate

Web : <https://www.mwworkstation.com/>

Tel : +86 13695211636

Mail : robbor@mwworkstation.com



Contents

<u>Components</u>	-----	1P
<u>Freestanding Desk</u>	-----	2P
<u>Manager table</u>	-----	3P
<u>Row 2 person Workstation</u>	-----	5P
<u>Opposite 4 person Workstation</u>	-----	7P
<u>X Shape Workstation Meeting</u>	-----	9P
<u>Table</u>	-----	11P
<u>Modesty Panel And</u> <u>Single Side Desk Screen</u>	-----	12P
<u>Face To Face Desk Screen</u>	-----	14P
<u>Side Desk Screen</u>	-----	16P




Components


FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

PARTS SHOW


[Leg]




[Side bar]




[Connection bar & Plastic snake]




[Mid-leg]




[Flat head screw M6*16]




[Flat head screw M8*16]




[Return cabinet]



[A wire box]




[B wire box]



[Countersunk cross topping screw M4*16]




[Connector]



[Countersunk cross topping screw M4*16]




[Support box]



[Countersunk cross topping screw M4*16]




[H750 desk screen]



[Flat head screw M5*12]




[H350 desk screen]



[Flat head screw M5*12]



[Modesty]



[Flat head screw M5*12]





Freestanding Desk

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS

<p>A</p> <p>M8*16mm</p> <p>2X</p>	<p>Round head cross screw M8*16</p> <p>16</p> <p>Ø17</p> <p>Ø8</p>	<p>CAUTION</p> <p>OK</p> <p>All at the top</p>	
<p>B</p> <p>M8*16mm</p>	<p>B</p>		
<p>Round head cross screw M6*16</p> <p>16</p> <p>Ø13</p> <p>Ø6</p>	<p>C</p> <p>M6*16mm</p>	<p>B Wire box</p> <p>M4*16mm</p>	<p>Countersunk cross topping screw M4*16</p> <p>16</p> <p>Ø6.4</p> <p>Ø4</p>
		<p>B</p>	



Manager Table

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS



<p>1X</p>	<p>Round head cross screw M8*16</p> <p>16</p> <p>Ø17</p> <p>Ø8</p>	<p>⚠ CAUTION</p> <p>OK</p> <p>All at the top</p>
	<p>Countersunk cross topping screw M4*16</p> <p>16</p> <p>Ø6.4</p> <p>Ø4</p>	
	<p>⚠ CAUTION</p>	



Manager Table

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS



[Flat head screw M5*12]	Countersunk cross topping screw M4*16



Row 2 person Workstation

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS







<p>A</p> <p>M8*16mm</p> <p>2X</p>	<p>Round head cross screw M8*16</p> <p>16</p> <p>Ø17</p> <p>Ø8</p>	<p>⚠ CAUTION</p> <p>OK</p> <p>All at the top</p>
<p>B</p> <p>M8*16mm</p> <p>B</p> <p>B</p> <p>C</p> <p>M6*16mm</p>		
<p>Round head cross screw M8*16</p> <p>16</p> <p>Ø17</p> <p>Ø8</p>	<p>M8*16mm</p>	



Row 2 person Workstation

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS

















V L

Opposite 4 person Workstation

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS


 <p>2X</p>	<p>Round head cross screw M8*16</p> 	<p> CAUTION</p> <p></p>  <p>All at the top</p>
 <p>B</p>	 <p>B</p>	 <p>B</p>
 <p>B</p>	 <p>C</p>	 <p>C</p>
<p>Round head cross screw M8*16</p> 	 <p>M8*16mm</p>	 <p>M6*16mm</p>




Opposite 4 person Workstation

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM


INSTALLATION STEPS



AB Wire box





M4*16mm



M4*16mm

Countersunk cross topping screw M4*16





X Shape Workstation

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS




<p>4X</p>	<p>Round head cross screw M8*16</p> <p>16</p> <p>Ø17</p> <p>Ø8</p>	<p>CAUTION</p> <p>OK</p> <p>All at the top</p>
<p>Round head cross screw M6*16</p> <p>16</p> <p>Ø13</p> <p>Ø6</p>	<p>Round head cross screw M6*16</p> <p>16</p> <p>Ø10</p> <p>Ø6</p>	<p>C</p>




X Shape Workstation

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM






INSTALLATION STEPS





Round head cross screw
M8*16



Countersunk cross topping
screw M4*16



Countersunk cross topping
screw M4*16












Meeting Table

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS








Modesty Panel And Single Side Desk Screen

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

PARTS SHOW








Modesty Panel And Single Side Desk Screen

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS







Face To Face Desk Screen

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM


PARTS SHOW



Screw Size

A :  M6×8mm

B :  M5×20









Face To Face Desk Screen

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS







Side Desk Screen


FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

PARTS SHOW



Screw Size

A :  M6×30mm








Side Desk Screen

FAST AND CONVENIENT INSTALLATION SYSTEM
DESK SYSTEM SCREEN SYSTEM

INSTALLATION STEPS



M & W

Web: mwworkstation.com

Mail: robbor@mwworkstation.com

Tel: +86 13695211636

WhatsApp: + 86 13695211636

Add: NO.3 Xingye North Road Dawotang Industrial
District Shishan Nanhai Foshan City Guangdong
P.R China



WhatsApp



Facebook



Instagram



Twitter



Pinterest



Linkein



YouTube